
## Annex-1



Circa 2009 Front Porch & Balcony


Brick column ±4 % incline needs leveling Also, verify footing cracks






Joint failure & damaged brick

Damaged deck board To be replace also rail system







Damage to crown & column base



Damage to balcony floor deck